

WMOLC	排数	每排引脚数	引脚样式	镀层选项	Q	选项	封装方式
	1,2排 3,4排	05,10,15,20, 25,30,35,40,45,50 (标准尺寸)	HX1 =通孔(从图表中指定) H02 =表面贴装 HM1 =混合技术	L =10μ"(0.25μm) 柱体镀金, 尾部镀雾锡		LC =锁定夹(需手动放置) P =拾取与放置焊盘(仅限02)	管装留空 TR =卷带包装(仅限02和HM1) FR =全卷带和卷(每卷必须订货最大数量,请联系Worldpo)

引脚样式		配合高度
WMOLC	WFOLC	
H01	H01	(5.97) .235
H11		(7.75) .305
H31		(11.43) .450

引脚样式	A	B
H01	(5.59) .220	(3.38) .133
H11	(7.34) .289	(3.66) .144
H31	(11.05) .435	

*加工条件会影响配合高度

